

ADDENDUM 2

ITB FM 29-18

REPLACEMENT OF 69 VAV BOXES FOR WATER & SEWER DEPARTMENT

This addendum will address the following question.

1. Is the Load and Voltage on the new VAV the same as the existing? The Voltage should be the same as the existing VAV, the Load needs to be as close as possible.

[This part of the page left blank intentionally]