

Okaloosa County Transition Plan for ADA Compliance

Location	Indenification of Physical Impediment to accessibility	Modifications/Corrective Actions To Be Undertaken	Estimated Cost	Begin Date	Completed Date	Responsible Individual
Beasley Park, FWB	Handrails too low on access ramp.	Raise handrails to meet FAC 4.8.5./ top of rail at 38", required 34"-38" - complete	\$0.00	1-96	2/10/2009	Parks Supervisor
Beasley Park, FWB	Bathroom stall doors do not have pull handles.	Install pull handles to meet FAC 4.13.9. - complete	\$50.00	1-96	2/12/2009	Parks Supervisor
Okaloosa Air Terminal, Eglin A.F.B.	Parking spaces are too small. Parking signs are wrong height. No curb cut	Parking lot under construction. Designed to meet FAC 4.6. - Complete	\$0.00	1-96	7/1/2018	Airport Director
Okaloosa Air Terminal, Eglin A.F.B.	Bathroom stalls are too small.	Rebuild stalls to meet FAC 4.17.3. -- New Building	\$5,000.00	1-97	7/1/2018	Facility Maintenance Dir.
Personnel Office, Crestview	Handle on restroom sink wrong type.	Install new handles, FAC 4.19.5 and 4.24.7. -- Complete	\$50.00	6-96	7/1/2018	Facility Maintenance Dir.
Purchasing, Crestview	Curb cut and sloped wrong	Rebuild curb cut, FAC 4.7 -- Complete	\$450.00	6-96	7/1/2018	Facility Maintenance Dir.
Blue Dolphin Beach Access, FWB	Bathroom stall door too small. (26"), Both men and women's.	Replace stall doors with doors that meet (32") FAC 4.17.5. - renovated - complete	\$600.00	1-96	11/1/2010	Parks Supervisor
Seashore Beach Access, FWB	Bathroom stall door too small (26"). Both men's and women's.	Replace stall doors with doors that meet FAC 4.17.5. (32")/ renovated - complete	\$600.00	1-96	1/1/2011	Parks Supervisor
Marler Park, FWB	Bathroom stall doors swing inside.	Reverse the door swing to meet FAC 4.17.5. / renovated - complete	\$200.00	1-96	11/8/2006	Parks Supervisor
Marler Park, FWB	Handrails do not meet the 1 1/4" - 1 1/2" diameter requirements	Install correct size handrails to meet FAC 4.8.5. / renovated - complete	\$1,000.00	1-96	11/8/2006	Parks Supervisor
Purchasing, Crestview	Restrooms not accessible	Use signage to direct public to accessible restrooms and fountains in complex. 4.30. -- Waiting to Remodel	\$75.00	6-96	7/1/2018	Facility Maintenance Dir.
Shoal River Park, Crestview	No handicapped access to restrooms and parking.No Signage. No walkways to ramps.	Demolish existing restrooms and rebuild according to FAC 4.22. / renovated new restroom constructed -- Complete	\$20,000.00	3-96	9/1/1996	Parks supervisor
State Attorney's Office	Restrooms not accessible.	Use signage to direct public to accessible restrooms and fountains in complex, FAC 4.6.4 and FAC 4.30. -- Complete	\$75.00	6-96	9/1/1996	Facility Maintenance Dir.
Veteran's Affairs, Crestview	Need directional signs to restrooms.	Install signage, FAC 4.6.4 and FAC 4.30. -- Complete	\$75.00	6-96	9/1/1996	Facility Maintenance Dir.
Agriculture Building/Crestview Old Bethal Rd	Signage in parking lot too low, FAC 4.6.4.	Raise sign to meet FAC 4.6.4. -- Complete	\$100.00	1-97	2/1/1997	Facility Maintenance Dir.
Agriculture Building/Crestview Old Bethal Rd	No handicap water cooler in building FAC 4.1.3 (10)	Install handicap water cooler to meet FAC 4.1.3 (10)	\$500.00	1-97	2/1/1997	Facility Maintenance Dir.
Beasley Park, FWB	Signs too low in parking lot.	Raise signs to meet FAC 4.6.4. / complete	\$100.00	1-97	7/3/1905	Parks Supervisor
Okaloosa County Courthouse	Signage in parking lot too low. 4.6.4. (FAC)	Raise signs to meet FAC 4.6.4. -- New facility under construction	\$100.00	1-97	7/1/2018	Facility Maintenance Dir.
Okaloosa County Courthouse	Bathroom sinks-handles are wrong type.	Replace handles to meet FAC 4.19.5. -- New facility under construction	\$100.00	1-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Sign height too low	Raise signs to meet FAC 4.6.4 -- Complete	\$100.00	1-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Dispensers & mirrors wrong height.	Remount dispensers and mirrors to right height to meet FAC 4.19.2, FIG 31 A -- Complete	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Grab bar in men's room too high.	Lower grab bar to meet FAC 6.17.6 -- Complete	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Water cooler too high	Lower water cooler to meet FAC 4.13.6 -- Complete	\$500.00	6-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Drain and hot water pipes unwrapped on sinks.	Wrap pipes to meet FAC 4.19.4. -- Complete	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Private Industry Council, FWB	Grab bars too high.	Lower grab bars to meet FAC 4.17.6. -- Bathroom needs to be remodelled	\$100.00	6-97	7/1/2018	Facility Maintenance Dir.
Private Industry Council, FWB	Sink handles wrong type.	Replace handles to meet FAC 4.19.5. -- Bathroom needs to be remodelled	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Private Industry Council, FWB	No wrapping on pipes under sinks.	Wrap pipe to meet FAC 4.19.4. -- Bathroom needs to be remodelled	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Okaloosa Air Terminal, Eglin A.F.B.	Bathrooms too small in men's room.	Enlarge bathroom stall to meet FAC 4.17.3. -- New Facility	\$2,500.00	9-97	10/1/1997	Airport Director
Blackwater Park, Baker	No walkways & ramps	Install walkways and ramps FAC 4.6 / complete	\$0.00		1/1/1998	Parks Supervisor
Blackwater Park, Baker	No handicapped access to restrooms and parking.	Demolish existing restroom and rebuild according to FAC 4.22. / complete	\$20,000.00	6-97	1/1/1999	Parks Supervisor
Blackwater Park, Baker	No signage	Install sign FAC 4.6.4. / complete	\$0.00		1/1/1998	Parks Supervisor
Blue Dolphin Beach Access, FWB	Approach to entrance door to bathrooms too small.	Relocate column to meet FAC 4.13.6, Fig 25 / complete	\$200.00	6-97	11/1/2010	Parks Supervisor
Okaloosa County Courthouse	No signage to restrooms FAC4.30.	Supply signage to meet FAC 4.30. -- New Facility Under Construction	\$150.00	3-97	7/1/2018	Facility Maintenance Dir.
Seashore Beach Access, FWB	Approach to entrance door too narrow because of the location of column. Both men's and women's bathrooms. (46")	Relocate column to meet FAC 4.13.6, Fig. 25. (48") / complete	\$200.00	1-96	7/1/2018	Parks Supervisor
Planning & Inspection, Crestview	Curb cut and sloped too steep	Rebuild curb cut to meet FAC 4.7. -- Complete	\$450.00	6-97	7/1/2018	Facility Maintenance Dir.
Planning & Inspection, Crestview	Handicapped parking inadequate.	Install signage and repaint space FAC 4.6, 4.7, 4.30. -- Complete	\$675.00	6-97	7/1/2018	Facility Maintenance Dir.
Shalimar Courthouse Annex	Signage in parking lot too low.	Raise signs to meet FAC 4.6.4. -- New Facility	\$200.00	1-97	7/1/2018	Facility Maintenance Dir.
Okaloosa Air Terminal, Eglin A.F.B.	Fire alarm pull stations too high. No visual alarms.	Lower pull station FAC 4.2.5 & 4.2.6. Install combination audio and visual alarms FAC 4.28. -- New Facility	\$3,000.00	9-97	7/1/2018	Airport Director
Private Industry Council, FWB	Sink in area too small for access.	Relocate sink to meet FAC 4.19.3. -- Bathrooms need to be remodelled	\$100.00	3-97	7/1/2018	Facility Maintenance Dir.
Private Industry Council, FWB	Door too small.	Replace door with correct size FAC 4.17.5. -- Bathrooms need to be remodelled	\$500.00	6-97	7/1/2018	Facility Maintenance Dir.
Marler Park, FWB	Toilet tissue holders too far from the commode.	Relocate holders to meet FAC 4.16.6. / complete	\$60.00	1-96	12/1/1998	Parks Supervisor
Marler Park, FWB	No towel dispenser inside stalls.	Install dispensers to meet FAC 4.22.7. / complete	\$200.00	1-96	12/1/1998	Parks Supervisor
Okaloosa County Courthouse	Ramp has no curb at least 2" from floor. FAC4.8.7.	Contract edge protection to meet FAC 4.8.7. -- New Facility Under Construction	\$600.00	6-97	7/1/2018	Facility Maintenance Dir.
Private Industry Council, FWB	Sign in parking lot too low.	Raise sign to meet FAC 4.6.4. -- Complete	\$100.00	1-97	7/1/2018	Facility Maintenance Dir.
Purchasing, Crestview	Parking spaces need remarking and signage.	Install signage and repaint parking space. FAC 4.6.3 and FAC 4.6.4. -- Complete	\$225.00	6-96	5/1/2005	Facility Maintenance Dir.
State Attorney's Office	Parking spaces need remarking and signage.	Install signal and repaint parking space FAC4.6.3 and FAC 4.6.4. -- Complete	\$225.00	6-96	5/1/2005	Facility Maintenance Dir.
State Attorney's Office	Curb cut and sloped wrong.	Rebuild curb cut, FAC4.7.	\$450.00	6-96	12/1/1998	Facility Maintenance Dir.
Okaloosa County Courthouse	No handicapped water cooler on 2nd floor. FAC4.1.3 (10)	Install handicap water cooler to meet FAC 4.1.3 (10) -- New Facility Under Construction	\$500.00	6-98	7/1/2018	Facility Maintenance Dir.
Shalimar Courthouse Annex	No handicapped restrooms in court room Jury room	Remodel Restrooms to meet FAC 4.16, 4.17, 4.18, 4.19 -- New Facility	\$3,000	9/1/1999	07/01/18	Facility Maintenance
Beasley Park, FWB	Toilet in men and women's restrooms wrong height.	Replace toilets in handicap stalls to meet FAC 4.16.3 - Complete	\$3,200.00	2015	07/01/18	Parks Supervisor
Beasley Park, FWB	Urinal too high	Lower urinal to meet FAC 4.18.2 - Complete	\$200.00	2015	07/01/18	Parks Supervisor
Blue Dolphin Beach Access, FWB	Urinal too high.	Lower urinal in men's room to meet FAC 4.13.6., Fig 25. -- Complete	\$300.00	2014	07/01/18	Parks Supervisor
Blue Dolphin Beach Access, FWB	Water fountain too high.	Lower water fountain to meet FAC 4.13.6. / complete	\$300.00	11/1/2010	9/30/2013	Parks Supervisor
Destin Airport	Remodel men and women's bathroom to meet ADA spec.	Upgrade bathrooms to meet FAC 4.16, 4.17, 4.18, 4.19.	\$4,000.00	9-97	Facility Closed	Airport Director
Destin Airport	Parking space too small, parking signs are wrong height.	Make parking spaces to comply with FAC 4.6.	\$300.00	6-97	Facility Closed	Airport Director
Shalimar Courthouse Annex	Men and women's restrooms too small	Rebuild or modify stalls to meet FAC 4.17.3. -- New Facility	\$4,000.00	9-97	2011	Facility Maintenance Dir.
Shalimar Courthouse Annex	Courtrooms C & D do not have accessible witness stands, lawyer's tables or juryboxes.	Build new courtrooms to meet the FAC for bldg. Construction. -- New Facility	\$3,000,000.00		2011	Okaloosa Co. Board of Commissioners.
Wayside Park, FWB	The approach on the ramps going into the shops are too steep.	Rebuild ramps to meet FAC 4.13.8. **	\$4,000.00		When funds are available.	Parks Supervisor
Wayside Park, FWB	Three (3) water fountains do not meet requirements.	Purchase and install fountains meeting FAC 4.15. / fountains removed with Leese renovations.	\$0.00	7-96	Inspected 2/5/2013	Parks Supervisor

Okaloosa County Transition Plan for ADA Compliance

Bob Sikes Airport	No parking spaces. No signs. No Curb cut. No accessible telephone	Install to meet FAC 4.6.	\$500.00	1-98	Facility Closed	Airport Director
Bob Sikes Airport	Bathrooms are too small.	Install to meet FAC 4.6.	\$10,000.00	1-98	Facility Closed	Airport Director
Bob Sikes Airport	Bathrooms too small	Remodel to meet ADA Specs. FAC 4.17.3.	\$5,000.00	1-98	Facility Closed	Airport Director
Wayside Park, FWB	Part of the handrails do not meet the 1 1/4" - 1 1/2" diameter requirements.	Replace sections of handrail not meeting FAC 4.8.5. / handrails renovated with Lessee renovations	\$800.00	7-96	Inspected 2/5/2013	Parks Supervisor
Veteran's Affairs, Crestview	Curb cut and sloped too steep.	Rebuild curb cut. FAC 4.7.	\$450.00	6-96	Moved	Facility Maintenance Dir.
Veteran's Affairs, Crestview	Parking space needs marking and signage.	Install signage and repaint parking space. FAC 4.6.3 and FAC 4.6.4.	\$225.00	6-96	Moved	Facility Maintenance Dir.
Wayside Park, FWB	Signage incorrectly mounted.	Relocate signs to meet FAC 4.30.6. / complete with Lessee renovations	\$100.00	7-96	Inspected 2/5/2013	Parks Supervisor
Wayside Park, FWB	Bathrooms need grab bar behind commodes.	Install grab bars to meet FAC 4.17.8. / complete with Lessee renovations	\$200.00	Jul-96	Inspected 2/5/2013	Parks Supervisor
Okaloosa Island Fishing Pier, FWB	Restrooms do not meet A.D.A. requirements.	Remodel bathrooms to meet FAC 4.16, 4.17, 4.18, 4.19. **	\$8,000.00	When funds are available.		Parks Supervisor
Okaloosa Island Fishing Pier, FWB	Access ramp is too steep	Build new ramp to meet FAC 4.8.**	\$5,000.00	When funds are available.		Parks Supervisor.
Wayside Park, FWB	No lavatory located by water closet.	Add lavatory to meet FAC 4.17 and 4.19, Fig 30. / renovated with Lessee renovations	\$0.00	Jul-96	Inspected 2/5/2013	Parks Supervisor
Wayside Park, FWB	No handicapped ramp to beach.	Build ramp to meet FAC 4.8. / renovated with Lessee renovations	\$0.00	Jul-96	Inspected 2/5/2013	Parks Supervisor